







WD1405





v013
02.12.2021
W. G.
[cm]



vinci
play










[cm]




vinci
play



32x M10x120 (K2)	34x M10x120 (K3)
	
	
NOT INCLUDED	


4x M8x120 (K2)	2x M8x120 (K3)
	
	
NOT INCLUDED	




[cm]









vinci
play





K1, K2 992124 x1	K3 992125 x1	K1, K2 P78 x2	K3 b219-2 x2	K1 142102 x6	K2 142108 x6	K3 142100 x6
------------------------	--------------------	---------------------	--------------------	--------------------	--------------------	--------------------







			PLYWOOD/ HDPE		HPL
98x	8x50 sxi	1x	CE6	1x	CL6
3x	WD50	2x	WD15	2x	WD16
2x	WD1	2x	WD35	2x	WD36
1x	WD14-4	1x	WD74	1x	WD75
1x	E39	1x	WD28 (S1)	1x	WD29 (S1)
1x	E34 (K1, K3)	1x	WD113 (S6)	1x	WD114 (S6)
1x	E35(K2)	1x	WD33	1x	WD34
1x	E38 (K2, K3)				
4x	WD52				
1x	SGL				
1x	GL (K2, K3)				
1x	V001				





PLYWOOD WD74 HPL WD75







8x50 sxi

[cm]











vinci
play



[cm]






vinci
play




[cm]




vinci
play



[cm]






vinci
play






PLYWOOD
WD33



HPL
WD34




8x50 sxi



8x50 sxi



E38




E39





[cm]



vinci
play



WD1



V001



[cm]



vinci
play