

SMB500 Surface Installation mounting box

Instruction Sheet
R10161GB0



Schneider Electric Fire & Security Oy

Sokerilinnantie 11 C
FI-02600 Espoo, Finland
Tel: +358 10 446 511
Website: www.schneider-electric.com
Document number: R10161GB0
Published: 15.07.2019

© 2019 – Schneider Electric. All Rights Reserved. This information is only to be used as guidance. Subject to changes and errors.

Contents

1	SMB500 Surface Installation Mounting box.....	4
----------	--	----------

1 SMB500 Surface Installation Mounting box

1. If surface mount conduit is to be used, predrill a hole in the side of the surface mount box at one of the drill centers provided.
2. Secure the surface mount box to the wall with screws and plastic anchors (provided) or to a junction box (screws not provided).
3. Wire the module according to the module instructions.
4. Assemble the module to the surface mount box with the short screws provided.
5. Fasten the cover plate to the module, using the screws provided with the module.

